


Solder this side Towards the



Single coil(ish) tones from a Bucker





All PCB boards are marked for

FletcherPickups wire colours.

R W G B relate to the four lead wires, Red, White, Green & Black on a Humbucker.

Bare wire to ground always.





Leave a gap between the board and the pot base when soldering.

Bend back the metal tag and solder this to the board Ground.

www.fletcherpickups.co.uk ben@fletcherpickups.co.uk